

**"Translated Copy of Building Safety Certificate from Kannada to English"**

GOVERNMENT OF KARNATAKA  
DEPARTMENT OF PUBLIC WORKS

N0.AEE/PWD/SD/ANEKAL/2022-23/105

Date: 06-06-2022

Office of the Assistant Executive Engineer  
Department of Public Works, Sub Division  
Anekal Taluk, Bangalore Urban District.

To,  
The Principal,  
St. Peter's International Public School.  
Heelalige, Chandapura  
Bangalore 560099.

Sir,

Sub: Issue of Building safety Certificate to St Peter's International Public School,  
building which comprises of Ground floor with three upper floors totally four floor  
building situated at Heelalige, Chandapura, Chandapura Taluk.- Regarding.

Ref: 1) Your Letter dated:25-05-2022  
2) Report of Dr. K Naresh,Dated:25-05-2022.  
3) This office letter No. AEE/PWD/SD/ANEKAL/2022-23/Dated: 06-06-2022.  
4) Your letter dated: 06-06-2022.

\*\*\*\*\*

With reference to subject cited above you have requested for issue Building safety  
Certificate to St Peter's International Public School, building which comprises of Ground floor  
with three upper floors totally four floors building situated at Heelalige, Chandapura,  
Chandapura Taluk.

Structural Stability Certificate was reported by conducting rebound Hammer test on the  
building of Ground and upper three floors for the said School building.

Said School Building was inspected on 03-06-2022 jointly with Principal of the School. On the  
Basis of Structural stability report and considering Structural stability as it was found Structurally stable,  
this Building safety certificate is issued subject to the conditions mentioned below and to implement  
following instructions time to time.

1. Plastering and Painting to existing roof slab and walls
2. Damp Proofing for all floors
3. Crack sealing at visible Structural Cracks at various Positions
4. Crack Sealing work at some Junctions of wall and beam
5. Damp Proofing works to toilet blocks and avoid leakage of water
6. Safety measure for Students and others
7. The Certificate is not valid incase of any natural disaster incase of cyclone, earth quake, Man  
made disaster, Any addition & Alteration of building.
8. This Certificate is Valid for 3 years



ATTESTED AS TRUE COPY

C. VIJAYAN, B.A., LL.B.,  
ADVOCATE & NOTARY  
Enrol No. MS 223(a)/95  
No. 156/41-A1, Taluk Office Road,  
Opp. To Traffic Investigation Wing,  
HOSUR - 635 109. Krishnagiri Dt.

.. 2..

9. Ownership of the Building is not responsible to PWD

Other than this, it is required to get inspected by the Fire safety department officials and get Fire Safety Certificate form Chief Fire safety officer.

Yours faithfully,

Sd/-

Assistant Executive Engineer  
Department of Public Works, Sub Division  
Anekal Taluk, Bangalore Urban District

‘Translated by Me.’

Advocate

“ Attested by Me “

Notary.



ATTESTED AS TRUE COPY

C. VIJAYAN, B.A., LL.B.,  
ADVOCATE & NOTARY  
Enrol No. MS 223(a)/95  
No. 156/41-A1, Taluk Office Road,  
Opp. To Traffic Investigation Wing,  
HOSUR - 635 109. Krishnagiri Dt.

ಕರ್ನಾಟಕ ಸರ್ಕಾರ  
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಂಖ್ಯೆ:ಸಕಾಅ/ಲೋಇ/ ಉವಿ/ಆನೆಕಲ್/2022-23/105      ದಿನಾಂಕ:06-06-2022

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ ರವರ ಕಛೇರಿ  
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಉಪ-ವಿಭಾಗ,  
ಆನೆಕಲ್ ತಾಲ್ಲೂಕು, ಬೆಂಗಳೂರು ನಗರ ಜಿಲ್ಲೆ

ರವರಿಗೆ,  
ಪ್ರಾಂಶುಪಾಲರು,  
ಸೆಂಟ್‌ಪೀಟರ್ಸ್ ಇಂಟರ್‌ನ್ಯಾಷನಲ್ ಪಬ್ಲಿಕ್ ಸ್ಕೂಲ್,  
ಹೀಲಿಗಿ, ಚಂದಾಪುರ,  
ಬೆಂಗಳೂರು-560 009

ಮಾನ್ಯರೇ,

ವಿಷಯ: ಆನೆಕಲ್ ತಾಲ್ಲೂಕು, ಹೀಲಿಗಿ ಚಂದಾಪುರದಲ್ಲಿರುವ ಸೆಂಟ್‌ಪೀಟರ್ಸ್ ಇಂಟರ್‌ನ್ಯಾಷನಲ್ ಪಬ್ಲಿಕ್ ಸ್ಕೂಲ್ ಕಟ್ಟಡದ ನೆಲಮಹಡಿ ಹಾಗೂ ಮೂರು ಮಹಡಿಗಳನ್ನು ಒಳಗೊಂಡಂತೆ ಒಟ್ಟು ನಾಲ್ಕು ಅಂತಸ್ಥಿನ ಕಟ್ಟಡ ಸುರಕ್ಷತೆ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ:1) ತಮ್ಮ ಪತ್ರ ದಿನಾಂಕ:25-05-2022

2) ಡಾ||ಕೆ.ನರೇಶ್ ಅವರ ವರದಿ ದಿನಾಂಕ:25-05-2022

3) ಈ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ:ಸಕಾಅ/ಲೋಇ/ಉಪವಿಭಾಗ/ಆನೆಕಲ್/2022-23/  
ದಿನಾಂಕ:06-06-2022.

4) ತಮ್ಮ ಪತ್ರ ದಿನಾಂಕ:06-06-2022

\*\*\*\*\*

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ ಸೆಂಟ್‌ಪೀಟರ್ಸ್ ಇಂಟರ್‌ನ್ಯಾಷನಲ್ ಪಬ್ಲಿಕ್ ಸ್ಕೂಲ್ ಕಟ್ಟಡದ ನೆಲಮಹಡಿ ಹಾಗೂ ಮೂರು ಮಹಡಿಗಳನ್ನು ಒಳಗೊಂಡಂತೆ ಒಟ್ಟು ನಾಲ್ಕು ಅಂತಸ್ಥಿನ ಕಟ್ಟಡಕ್ಕೆ ಸುರಕ್ಷತೆ ಪತ್ರವನ್ನು ನೀಡಲು ಪತ್ರದಲ್ಲಿ ಕೋರಿರುತ್ತಿರಿ.

ನೆಲ ಮಹಡಿ ಹಾಗೂ ಮೂರು ಮಹಡಿಗಳ ಕಟ್ಟಡವನ್ನು ತಪಾಸಣೆ ನಡೆಸಿ ರಿಬೋರ್ಡ್ ಹ್ಯಾಮರ್ ಟೆಸ್ಟ್‌ಗಳನ್ನು ಮಾಡಿ ವರದಿಯನ್ನು ನೀಡಿದ್ದು ಸದರಿ ಶಾಲಾ / ಕಾಲೇಜು ಕಟ್ಟಡದ Structurally Stability Certificate ಇರುವುದನ್ನು ವರದಿ ನೀಡಿರುತ್ತಾರೆ.

ಮುಟ..2ಕ್ಕೆ

ದಿನಾಂಕ:03-06-2022 ರಂದು ಸದರಿ ಕಟ್ಟಡವನ್ನು ಕಾಲೇಜಿನ ಪ್ರಾಂಶುಪಾಲರೊಂದಿಗೆ ಜಂಟಿಯಾಗಿ ತಪಾಸಣೆ ನಡೆಸಲಾಯಿತು. Structurally Stability ತೃಪ್ತಿಕರವಾಗಿರುತ್ತದೆ ಎಂದು ನೀಡಿರುವ ವರದಿಯನ್ನು ಪರಿಗಣಿಸಿ, ಒಟ್ಟು ನಾಲ್ಕು ಅಂತಸ್ತಿನ ಕಟ್ಟಡವು ಮೇಲ್ನೋಟಕ್ಕೆ Structurally Stable ಇದೆ ಎಂದು ಕಟ್ಟಡ ಸುರಕ್ಷಾ ಪತ್ರವನ್ನು ಈ ಕೆಳಕಂಡ ನಿರ್ಬಂಧನೆಗೊಳಪಟ್ಟು ಹಾಗೂ ಈ ಕೆಳಕಂಡ ಸೂಚನೆಗಳನ್ನು ಕಾಲಕಾಲಕ್ಕೆ ಅಳವಡಿಸಿಕೊಳ್ಳಲು ಸೂಚಿಸಲಾಗಿದೆ.

1. Plastering and Painting to existing roof slab and walls.
2. Damp Proofing for all floors
3. Crack sealing at visible structural cracks at various positions.
4. Crack sealing works at some junctions of wall and beam
5. Damp Proofing works to toilet blocks and avoid leakage of water
6. Safety Measures for students and others.
7. The Certificate is not valid incase of any natural disaster incase of cyclone, earth quake, Man Made disaster, Any Addition & Alteration of building.
8. This Certificate is valid for 3 years.
9. Ownership of the building is not responsible to PWD

ಉಳಿದ ಸಂಬಂಧಿಸಿದಂತೆ ಅಗ್ನಿಶಾಮಕ ಇಲಾಖೆಯ ಅಧಿಕಾರಿಗಳ ವತಿಯಿಂದ ಪರಿಶೀಲಿಸಿ Fire Safety Certificate ನ್ನು ಮುಖ್ಯ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿಯಿಂದ ಪಡೆಯತಕ್ಕದ್ದು.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಅಭಿಯಂತರರು,

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಉಪ-ವಿಭಾಗ,

ಆನೇಕಲ್ ಬೆಂಗಳೂರು ನಗರ ಜಿಲ್ಲೆ.

**ASSISTANT ENGINEER**  
P.W.D. SUB - DIVISION  
ANEKAL TALUK,  
BANGALORE URBAN DISTRICT